



# CABS-CT1-xxxx



NeedleError設定用ボタン (φ2穴)

LED表示部

取付穴 (φ4.2)



CONNECTOR PINOUT	
1	Cleaning out
2	ChargeSNS out
3	Needle Error out
4	HEATER out
5	Hi/Stop in
6	Out signal GND
7	Out signal power
8	Ground
9	Needle Error Adjust1
10	Needle Error Adjust2
11	DC 24V
12	DC 0V



CABS-TR1接続コネクタ

電源・信号ケーブル接続コネクタ